

DUPRO INSPECTION REPORT

Comprehensive Mid-Production Assessment

Factory : Hebei Textiles - China



Powered by Silq Inspection Services

For more information visit www.onesilq.com/inspections

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment



Quality Checkpoints	Body Colour	OK
	Shade Check	OK
	Sewing Quality check	OK
	Matching buyer's tech pack/spec	OK
	Compared to Approved Sample	OK

Fabric Check	Fabric quality	OK
	GSM/Weight as specified	OK
	Color shade matches standard	OK
	Fabric Touch Handfeel	OK
	Fabric Odour	OK

Artwork Check	Print/embroidery quality	OK
	Print/embroidery Colour	OK
	Print/embroidery Size	OK
	Print / embroidery Rubbing check	OK
	Print/embroidery Handfeel	OK
	Print/embroidery Odour	OK

Trims, Accessories & Labelling	Main Label	OK
	Size Label	OK
	Wash Care Label	OK
	Tab Label	OK
	Additional Label	N/A
	Placement of labels	OK
	Trims securely attached	OK
	Drawcord / Rope / Eyelet	N/A
	Elastic Quality	N/A
	Buttons	N/A
	Hangtags / Barcode Sticker	OK
	Polybag size / Quality	N/A



General Information

FACTORY NAME & ADDRESS

HEBEI TEXTILES

BUYER/BRAND

SILQ

INSPECTION DATE

04/17/2026

PURCHASE ORDER NO.

153430

STYLE NO. / ARTICLE NO.

55734FQ/KG/TW

ITEM DESCRIPTION

Quilt set

PRODUCT MATERIAL

100% Polyester

COLOUR

Multi - AOP Printed

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment



Functionality Check	Ease of wear/removal	OK
	Fit on mannequin or model	OK
	Functionality of Buttons / Zip / Elastic / Velcro / Hook /Rope	OK
	Overall aesthetic appeal	OK

Packing Quality & Presentation	Folding as per buyer requirement	NA	Packing not yet started
	Carton Quality	NA	
	Carton Size	NA	
	Carton Marking	NA	

Inspection Summary	Operation Being Inspected	: Under Production
	Production Status (%)	: 2 % Production Completed / Balance under production
	Total Qty Inspected in In-Line	: 24
	Overall Product Quality Status	: Needs Improvement during production

For Internal use only by Silq

SILQ ID
Silq-9750797

SILQ INSPECTOR
Story Guo

REPORT DATE
04/17/2026

REVIEW DATE
04/17/2026

SECONDARY REVIEW BY

Mr. Sundar
Senior Manager
Global Inspections

Inspector Comments & Recommendations

1. PLS TAKE CARE WHILE HANDLING THE WHITE GARMENTS TO AVOID STAINS
2. TAKE CARE IN LABEL ATTACHMENTS AND AVOID TILTING / SLANTING
3. AVOID FINISHING DEFECTS SUCH AS - UNTRIMMED THREADS / STAINS - PLS TAKE CARE IN CHECKING
4. AVOID SEWING DEFECTS SUCH AS SKIP STITCH , DOUBLE JOINT, MIS STITCH - PLS REPAIR OR REPLACE THE DEFECTS BEFORE PACKING

SILQ QC HIGHLIGHTED THE DEFECTS IDENTIFIED DURING THE IN-LINE INSPECTION, EXPLAINED THEM TO THE FACTORY IN DETAIL, AND INSTRUCTED THE FACTORY TO RECTIFY ALL THE ABOVE-MENTIONED ISSUES BEFORE THE FINAL INSPECTION

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment




Part Dimensions	Unit Cms	Tol. Limit + / -	MEASUREMENTS																										
			TWIN			QUEEN			KING			Spec			I			II			Spec			I			II		
			Spec	I	II	Spec	I	II	Spec	I	II	Spec	I	II	Spec	I	II	Spec	I	II	Spec	I	II	Spec	I	II			
QUILT SIZE (inches):			70	0	0	90	0	0	108	0	0																		
			90	0	0	92	- 1/2	- 1/4	92	0	0																		
PILLOW SIZE(inches):			20	1/2	1/4	20	1/2	1/2	20	1/4	1/4																		
			26	1/4	1/4	26	1/4	1/4	36	1/4	1/4																		
QUILT WEIGHT(KG)			70*90	1.496	1.501	90*92	1.929	1.932	108*92	2.277	2.269																		
PILLOW WEIGHT(G)			20*26	101	99	20*26	103	102	20*36	132	134																		

MEASUREMENT COMMENTS :

1. The Measurements are found within tolerance

ACCESSORIES AND TRIMS



QUILT MAIN LABEL



QUILT LAW LABEL



PILLOW LABEL



PRODUCT VIEW



QUILT FRONT



QUILT BACK

GENERAL IMAGES



PILLOW FRONT VIEW (20*36in)



PILLOW BACK VIEW (20*36in)



PILLOW FRONT VIEW (20*36in)



PILLOW BACK VIEW(20*36in)



ARTWORK VIEW



ARTWORK COMPARED TO APPROVED SAMPLE

GENERAL IMAGES



QUILT ARTWORK VIEW



QUILT ARTWORK VIEW



QUILT ARTWORK VIEW



QUILT ARTWORK VIEW



BOTTOM HEM VIEW



BOTTOM HEM INSIDE VIEW

QUALITY CHECK IMAGES



PRODUCT SIZE CHECK



PRODUCT SIZE CHECK



PRODUCT SIZE CHECK



PRODUCT SIZE CHECK



PRODUCT WEIGHT CHECK



PRODUCT WEIGHT CHECK

QUALITY CHECK IMAGES



SHADE CHECK IN BULK



PRINT DRY RUB CHECK



ODOUR CHECK



INTERNAL FILLING CHECK



PULLTEST



BULK IN PRODUCTION LINE

DEFECT IMAGES



Findings : Snagging yarn
Corrective Action : It has been informed to the factory that they should pay attention to the fabric issues during production.



Findings : pillow is sewn too tightly
Corrective Action : Machine setting is too tight - adjust to loosen it slightly