


IN-LINE INSPECTION REPORT

Comprehensive Mid-Production Assessment

Silq Fashions - Chennai, India



Silq In-line Inspection Report Comprehensive Mid-Production Assessment



Quality Checkpoints	Body Colour	ок	
	Shade Check	ок	
	Sewing Quality check	ок	
	Matching buyer's tech pack/spec	ок	
	Compared to Approved Sample	ок	
Fabric Check	Fabric quality	ок	
	GSM/Weight as specified	ок	
	Color shade matches standard	ок	
	Fabric Handfeel	ок	
	Fabric Odour	ок	General Information
Artwork Check	Print/embroidery quality/AOP	ок	FACTORY NAME & ADDRESS
Griddi	Print/embroidery Colour/AOP	ок	Silq Fashions
	Print/embroidery Size/AOP	ок	BUYER/BRAND
	Print / embroidery Rubbing check /AOP	ок	Silq
	Print/embroidery Handfeel/AOP	ок	INSPECTION DATE
	Print/embroidery Odour/AOP	ок	11/28/2025
Trims, Accessories & Labelling	Main Label	ок	PURCHASE ORDER NO.
	Size Label	ок	Silq - 3012
	Wash Care Label	ок	STYLE NO. / ARTICLE NO.
	Tab Label	ок	S5153
	Additional Label	ок	ITEM DESCRIPTION
	Placement of labels	ок	MENS T-SHIRT
	Trims securely attached	ок	PRODUCT MATERIAL
	Drawcord / Rope / Eyelet	NA	100% COTTON
	Elastic Quality	NA	COLOUR
	Buttons / Button Hole	NA	ALLOVER PRINTED
	Hangtags / Barcode Sticker	ок	
	Polybag size / Quality	ок	

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment



Functionality Check	Ease of wear/removal	ок	For Internal use only by Silq
	Fit on mannequin or model	ОК	SILQ ID
	Functionality of Buttons / Zip / Elastic / Velcro / Hook	ок	Silq-6120987
	Overall Aesthetic appeal	ОК	SILQ INSPECTOR
Packing Quality &	Folding as per buyer requirement	ОК	Mr. Mani
Presentation	Carton Quality	ОК	
	Carton Size	ок	REVIEW DATE
	Carton Marking	ОК	11/28/2025
Inspection Summary	Operation Being Inspected	Under Production	SECONDARY REVIEW BY
	Production Status (%)	: 30 % Production Completed / Balance under production	Mr. Sundar Senior Manager
	Total Qty Inspected in In-Line	40 pcs	Global Inspections
	AQL Standard	2.5	

Inspector Comments & Recommendations

- 1. Compared to Approved Pre- production sample.
- 2. Garment should be symmetrical
- 3. Main label print s/b centered and straight
- 4. Main label print s/b centered and straight
- 5. Side seam should be narrow and even
- 6. Avoid twisting at bottom hem
- 7. Neck Wrinkles should be strictly avoided
- 8. Both Sleeves should be even
- 9. Skip stitches should be avoided and adjust machine settings
- 10. Neck Band should be even all around
- 11. Pleats should be avoided at shoulder + sleeve joints
- 12. Avoid Raw Edges inside Bottom hem / sleeve hem adjust the Flat lock machine settings
- 13. Take care and rectify print mistakes
- 14. Gsm was checked on rejected garment
- 15. Measurments should be within tolarance

SILQ QC HIGHLIGHTED THE DEFECTS IDENTIFIED DURING THE IN-LINE INSPECTION, EXPLAINED THEM TO THE FACTORY IN DETAIL, AND INSTRUCTED THE FACTORY TO RECTIFY ALL THE ABOVE-MENTIONED ISSUES BEFORE THE FINAL INSPECTION

Silq In-line Inspection Report Comprehensive Mid-Production Assessment



	Unit			MEASUREMENTS Output Output																						
Part Dimensions		Tol. Limit		S			М			L			XL			2XL			3XL							
Front body length - from hps to	hem	+/-	Spec 29 1/4	OK	ОК	Spec 30 1/4	OK	+1/4	Spec 31 1/4	OK	+1/2	Spec 32 1/4	OK	ОК	Spec 33 1/4	-1/2	-3/4	Spec 34	OK	+1/4	Spec	ı	II	Spec	I	II
edge																										
Shoulder slope - measure 2pt		1/8	1 5/8	ОК	OK	15/8	ОК	OK	1 5/8	OK	OK	1 5/8	OK	OK	15/8	OK	OK	1 5/8	OK	OK						
Shoulder seam forward		1/8	1/2	+1/2	+1/2	1/2	ОК	-1/2	1/2	ОК	+1/4	1/2	-1/2	-1	1/2	ОК	+1/4	1/2	+1/4	+1/2						
Neck width - seam to seam		1/4	7 3/4	ОК	ОК	8	-1	OK	8 1/4	-1	OK	8 1/2	ОК	-1	9	ОК	-1	9 1/2	ОК	ОК						
Front neck drop - hps to seam		1/4	3 3/4	+1/8	OK	4	+1/4	+1/8	4 1/4	ОК	OK	4 1/2	+1/4	+1/8	5	OK	ОК	5 1/2	-1/4	ОК						
Collar height - rib		1/8	3/4	+1/2	+1/4	3/4	ОК	+1/4	3/4	ОК	OK	3/4	+1/2	+1/4	3/4	+1/4	+1	3/4	ОК	+1/4						
Across front - 6" from hps seam seam	to	3/8	18 1/4	-1/2	-1	19	-1	-1	20	-1	-1 1/8	21	-1/2	-1	21	-1	-3/4	21	-1	-1 1/2						
Chest width - 1" below armhole		1/2	20 1/2	-1/8	ОК	22	ОК	+1/4	24	+1/4	+1/4	26	+1/4	ОК	26	-1/4	-3/8	26	OK	+1/4						
Bottom sweep opening - straigh	t	1/2	20 1/2	ок	+1/8	22	+3/8	+1/4	24	ОК	ОК	26	+1/8	ОК	26	ОК	ОК	26	+1/4	ОК						
Hem height		1/8	3/4	OK	ОК	3/4	+1/4	ОК	3/4	-1/4	ОК	3/4	-1/2	-1/2	3/4	ОК	-1/4	3/4	+1/4	ОК						
Back body length - from hps to e	edge	1/2	29 1/2	+1/4	ОК	30 1/2	ОК	ОК	31 1/2	+1/4	+1/2	32 1/2	-1/4	-1/4	32 1/2	+1/4	ОК	32 1/2	+1/4	+1/4						
Back neck drop - hps to seam		1/4	2	ОК	-1/4	2	-1/4	ОК	2	+1/4	+1/4	2	ОК	ОК	2	-1/4	ОК	2	ОК	ОК						
Across shoulder - seam to seam		3/8	19 7/8	ОК	-1/8	20 5/8	ОК	+1/8	21 5/8	-1/8	ОК	22 5/8	+1/8	ОК	22 5/8	ОК	ОК	22 5/8	ОК	+1/4						
Across back - 6" from hps seam seam	to	3/8	19	OK	ОК	19 3/4	OK	ОК	20 3/4	+1/8	OK	21 3/4	OK	OK	21 3/4	ОК	ОК	21 3/4	+1/8	ОК						
Armhole - straight		3/8	9 3/4	+1/4	ОК	10 1/4	+1/4	ОК	10 3/4	ОК	+1/8	11 1/4	+1/4	ОК	11 1/4	+1/8	ОК	11 1/4	-1/8	OK						
Sleeve length - short - armhole tedge	0	3/8	8 1/4	OK	OK	8 1/2	ОК	OK	8 3/4	ОК	OK	9	OK	OK	9	OK	OK	9	OK	OK						
Sleeve opening		1/4	7	+1/4	ОК	7 1/4	+1/4	ОК	7 1/2	ОК	+1/8	7 3/4	+1/4	ОК	7 3/4	+1/8	ОК	7 3/4	-1/8	ОК						
Sleeve hem height		1/8	3/4	ОК	ОК	3/4	ОК	ОК	3/4	ОК	ОК	3/4	ОК	ОК	3/4	ОК	ОК	3/4	ОК	ОК						


MEASRURMENT COMMENTS:

1. The Specs Marked in Yellow are out of Tolarance

GENERAL IMAGES



MAIN LABEL + SIZE LABEL + WASHCARE LABEL



SIDE LABEL



COMPARED TO APPROVED SAMPLE - FRONT



COMPARED TO APPROVED SAMPLE - BACK



GARMENT FRONT



GARMENT BACK

GENERAL IMAGES



NECK VIEW



AOP PRINT COMPARED TO APPROVED SAMPLE



BULK IN PRODUCTION LINE



AOP PRINT VIEW



SHADE CHECK IN BULK



BULK IN IRONING LINE

QUALITY CHECK IMAGES



NECK STRETCH CHECK



ODOUR CHECK



PRINT DRY RUB CHECK



LABEL SEWING CHECK



SIDE SEAM STITCHING QUALITY CHECK



PRINT PEEL OFF CHECK

Silq In-line Inspection Report Comprehensive Mid-Production Assessment

DEFECT IMAGES





: Botom hem Wavy **Findings**

Corrective Action : Machine setting is too tight - adjust to loosen it slightly



: Neck Rib width eneven **Findings**

Corrective Action : Neck Rib should be cut evenly in the cutting



Findings : Neck Shape uneven

Corrective Action : Take care while attaching neck rib



Findings : Shoulder Slope not even on b

Corrective Action: Maintain the stitching allowance evenly in shoulder joining