Pre-Shipment Inspection Report

Comprehensive On-Site Assessment

SEN BAO

Powered by Silq Inspection

For more information visit
www.onesilq.com/inspections

SUMMARY

Pre-shipment Inspection Report as on 28 January 2026

SILQ

BRAND
SILQ

ORDER QTY
1344

INSPECTION LOCATION
QINGYUAN - CHINA

EST. SHIPPING QTY
1344
(as per packing list)

TRADING AGENT / FACTORY
SEN BAO

EX-FACTORY DATE
10/02/2026

PO NUMBER
04721

STYLE NO. & DESC.
ELEANOR

PRODUCTION MATERIAL / CONSTRUCTION
Exterior coating - 100% Polyurethane
Exterior base fabric: 100% Recycled Polyester
Lining: 100% Recycled Polyester

STYLE COLOR & CODE
BLACK, HAZELNUT

INSPECTION IMAGES LINK
NA

TOTAL CARTONS
112

TOTAL INSPECTED QTY (AS PER AQL LEVEL)
148 PCS
of 1344 PCS

INSPECTION RESULT
PASS

ISSUE TYPE / NO. OF ISSUES FOUND	STATUS & AQL LEVEL	ACCEPTED DEFECT LIMITS BY AQL
MAJOR DEFECTS 5	ACCEPTED	defects within AQL 2.5 — upto 8 defects allowed
MINOR DEFECTS 5	ACCEPTED	defects within AQL 2.5 — upto 10 defects allowed
CRITICAL DEFECTS Nil	ACCEPTED	defects within AQL 0.1 — upto 0 defects allowed

SILQ'S OBSERVATION		REMARKS
WORKMANSHIP (as per AQL Level)	OK	
PRODUCT CONFORMITY	OK	
MEASUREMENTS	OK	
ONSITE TESTS	OK	
PACKING	OK	

NOTES & COMMENTS

1. Approval sample received and returned to factory
2. PO / Tech Pack / Measurement Chart recieved from Client
3. Client to confirm release of goods

The Defects found by the Silq QC during inspection was shown to the factory - The Silq QC advised factory to Repair/Replace/ Reject these defects before dispatch of the goods

SILQ ID
Silq-4154531

REVIEW DATE
00/01/1900

REPORT DATE
00/01/1900

SILQ INSPECTOR
WOLKER HUANG

SECONDARY REVIEW BY
Mr. Sundar
Senior Manager - Global Inspections

FACTORY REPRESENTATIVE / DESIGNATION
Mr Lin - QC

DISCLAIMER ** THE RESULT REFLECTS OUR FINDINGS FROM THE RANDOMLY DRAWN PIECES FROM THE TOTAL QUANTITY. THIS REPORT DOES NOT RELIEVE SELLER/MANUFACTURER/ EXPORTER / FACTORY FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE BUYER'S RIGHT FOR COMPENSATION FOR ANY APPARENT AND/OR HIDDEN DEFECT NOT DETECTED DURING INSPECTION OR OCCURRING THEREAFTER. ANY UNAUTHORIZED ALTERATION, FORGERY OR FALSIFICATION OF THE CONTENT OR APPEARANCE OF THIS DOCUMENT IS UNLAWFUL AND OFFENDERS MAY BE PROSECUTED TO THE FULLEST EXTENT OF LAW.**

PRODUCT CONFORMITY (IN COMPARISON TO APPROVED SAMPLE AND TECH PACK INSTRUCTIONS)

DESCRIPTION	CONFORMITY	REMARKS
Style	CONFORM	
Product Quality / Weight	CONFORM	
Product Colour	CONFORM	
Product Construction Quality (body / making)	CONFORM	
Dyeing / Treatment / Wash / Handfeel	CONFORM	
Artwork / Application Size / Colour / Placement (print / emb / other embellishments)	CONFORM	
Labeling (main label / size label / washcare label / other labels)	CONFORM	
Fit	N/A	
Hangtag / Price tag / Barcode Stickers	CONFORM	
Product Odour	CONFORM	
Product Shades (body and artwork – piece-to-piece consistency in bulk)	CONFORM	
Accessories / Trims: Quality (snap buttons / velcro / zipper / buttons / zip puller / tapes / elastic/ wheels)	CONFORM	
Accessories / Trims: Functionality (snap buttons / velcro / zipper / buttons / zip puller / tapes / elastic/ wheels)	CONFORM	
Packing	CONFORM	
Others	CONFORM	

FRONT

APPROVED SAMPLE | BULK

BACK

APPROVED SAMPLE | BULK

PRODUCT CONFORMITY IMAGES - ACCESSORIES AND TRIMS

LOGO

STYLE NAME

TSSA/COO LABEL

LOGO

STYLE NAME

TSSA/COO LABEL

PRODUCT CONFORMITY IMAGES

HANG TAG



HANG TAG

D RING

STRAPS

HARDWARES

MAGNETIC BUTTON

ONSITE TESTS IMAGES

PULL TEST - SEAM SLIPPAGE

PULL TEST - ZIPPER



PULL TEST - D RING

PULL TEST - DOG CLIP

PULL TEST - LOGO

FUNCTION TEST - MAGNETIC BUTTON

WORKMANSHIP AUDIT - INSPECTION DETAILS | NO. OF UNITS INSPECTED 148 PCS (AS PER AQL LEVEL - MAJOR = 2.5 / MINOR = 4)

DEFECT CLASSIFICATION	DEFECT DESCRIPTION	MAJOR DEFECT (AQL 2.5)	MINOR DEFECT (AQL 4.0)	CRITICAL	REMARKS
Pressing Defects	Crease marks	2	1		
General Defect	Cracked	2	0		
Sewing Defect	Unmatched seam	1	1		
Sewing Defect	Wavy zipper	0	2		
General Defect	Scratch	0	1		
Total Defective Units Found		**5**	**5**	**0**	
Maximum defects allowed		**8**	**10**	**0**	

DEFECT IMAGES

MAJOR

Crease marks

MAJOR

Cracked

MAJOR

Unmatched seam

MINOR

Wavy zipper

MINOR

Scratch

NA

MEASUREMENT AUDIT

Size & Measurements (Measurement Checked 2 pcs / size)

PART DIMENSIONS	cms	TOL. LIMIT +/-	ONE SIZE		
Bag length at the bottom			26	0.5	0.5
Bag length at the opening			20.5	0.3	0.3
Bag width			6	-0.2	-0.2
Bag height			13.5	0	0

PACKING AUDIT

DESCRIPTION	DETAILS	REMARKS
Order Quantity	1344	
Packed Quantity	1344	
Quantity Remarks - Shortage / Excess	0	
Quantity Shortage/Excess Approval from Client	N/A	
Total Cartons	112	
Carton Numbers	N/A	There is no carton number on the cartons
Final Packing Approval from Client	N/A	
Packing Status at the time of Inspection - Is it 100% packed?	NO	
If " Packing" status is NO, Cartons Packed / % Packed:	NO	Total 90 cartons around 80.36% of bulks were packed during inspection.
Carton Dimension (as per requirement)	OK	
Carton Marking - Length Side	OK	
Carton Marking - Width Side	OK	
Carton Quality	OK	
Polybag Quality	OK	
Polybag Size	OK	
Carton Weight within specified acceptable limits	YES	
Total Cartons Inspected	14	
Carton Sizes Used	OK	**56 X 39 X23CM**

MASTER CARTON NUMBERS INSPECTED BY SILQ

PO NUMBER / COLOUR	CARTON NUMBERS	TOTAL CARTONS INSPECTED
PO - 04721	There is no carton number on the cartons	14
	Total	14

PACKING PICTURES

CARTON MARKING

CARTON MARKING



BARCODE LABEL



BARCODE LABEL

INSIDE CARTON



PACKING

PACKING IMAGES

UPC LABEL

POLYBAG

POLYBAG

ANTI-MILDEW SHEET

DUST BAG

CARE LABEL FOR THE DUST BAG