

DUPRO INSPECTION REPORT

Comprehensive Mid-Production Assessment

Factory : VEDHU INDUSTRIES



Powered by Silq Inspection Services



For more information visit www.onesilq.com/inspections

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment

| Visual & Physical Inspection | | |
|---|----|--|
| Model | OK | |
| Surface Finish | OK | |
| Logo / Branding Placement | OK | |
| Keypad / Touch Panel | OK | |
| Components Check | OK | |
| Front & Back Alignment | OK | |
| Card / Key Check | OK | |
| No gule marks / dust | OK | |
| No sharp edges / molding defect | OK | |
| Uniform color / texture | OK | |
| Brand Logo / Barcode Check | | |
| Brand Logo on Product | OK | |
| Brand Logo Placement | OK | |
| Brand Logo Colour | OK | |
| Brand Logo Size | OK | |
| Brand Logo on Product Packing | OK | |
| Brand Logo on Product Packing Size / Font | OK | |
| Functionality Check | | |
| Fingerprint Recongnition | OK | |
| Password / Keypad Response | OK | |
| RFID / Card access working | OK | |
| Mobile App Check | OK | |
| Bluetooth / Wi-Fi Connectivity | OK | |
| Manual key override working | OK | |
| Lock / Unlock cycle work | OK | |
| Electrical & Battery Check | | |
| Power ON/OFF function | OK | |
| Battery Installed check | OK | |
| Low Battery Indicator working | OK | |
| Battery Charging Check | OK | |
| Wiring condition | OK | |
| Stable power supply | OK | |

PRODUCT VIEW



General Information

FACTORY NAME & ADDRESS
VEDHU INDUSTRIES

BUYER/BRAND
SILQ

INSPECTION DATE
04.10.2026

PURCHASE ORDER NO.
PO81714

STYLE NO. / ARTICLE NO.
RCV-140911

ITEM DESCRIPTION
SMART LOCK

PRODUCT MATERIAL
Plastic, Stainless steel, Aluminum alloy

COLOUR
SUNSET COPPER

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment



| | | |
|--|----------------------------------|----|
| Door Installation Simulation Test | Proper fit on test | OK |
| | Smooth door closing and locking | OK |
| | Bolt aligns correctly | OK |
| | Multiple cycle (open/close) test | OK |

| | | |
|---|-----------------------------------|----|
| Packing Quality & Presentation | All accessories | OK |
| | Proper inner tray/foam protection | OK |
| | Correct carton labeling | OK |
| | No damage to packaging | OK |

| | | |
|---------------------------|--------------------------------|---|
| Inspection Summary | Operation Being Inspected | : Under Production |
| | Production Status (%) | : 50 % Production Finished & Balance 50% under Production |
| | Total Qty Inspected in In-Line | : 10 PCS |
| | Overall Product Quality Status | : Improvement needed in Final Finishing and Packing |

For Internal use only by Silq

SILQ ID
SILQ-8417514

SILQ INSPECTOR
A. MANIKANDAN

REPORT DATE
04.10.2026

REVIEW DATE
04.11.2026

SECONDARY REVIEW BY
**Mr. Sundar
Senior Manager
Global Inspections**

Inspector Comments & Recommendations

1. Avoid Scratch Marks - Handle with care during production
2. BlueTooth is not getting paired in few units - pls repair / replace those units and take care to process in correctly
3. Ensure battery is packed alongwith all the units.
4. Barcode is not scannable in some units during Dupro - pls replace it with correct barcode stickers

SILQ QC HIGHLIGHTED THE DEFECTS IDENTIFIED DURING THE IN-LINE INSPECTION, EXPLAINED THEM TO THE FACTORY IN DETAIL, AND INSTRUCTED THE FACTORY TO RECTIFY ALL THE ABOVE-MENTIONED ISSUES BEFORE THE FINAL INSPECTION

GENERAL IMAGES



PRODUCT VIEW



PRODUCT VIEW




PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW

DIMENSION CHECK IMAGES



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



KEYS / LOCK & SCREW



PRODUCT VIEW

GENERAL IMAGES




PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW

GENERAL IMAGES



PRODUCT VIEW




PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW




PRODUCT VIEW

DEFECT IMAGES



Findings : Scratch Mark at Body

Corrective Action : Avoid Scratch Mark and take utmost care while handling




Findings : Stain Mark at Body

Corrective Action : Please avoid the stain mark.




Findings : Scratch Mark at Body

Corrective Action : Avoid Scratch Mark and take utmost care while handling



Findings :

Corrective Action :



Findings :

Corrective Action :



Findings :

Corrective Action :