

Pre-Shipment Inspection Report

Comprehensive On-Site
Assessment

Factory : Becky Technologies



Powered by Silq Inspection

For more information visit
www.onesilq.com/inspections

SUMMARY

Pre-Shipment Inspection Report as on 14 April, 2026

SILQ SMART LOCK

BRAND SILQ	ORDER QTY 350
INSPECTION LOCATION Guangdong, China.	EST. SHIPPING QTY 350 <small>(as per packing list)</small>
TRADING AGENT / FACTORY	EX-FACTORY DATE
PO NUMBER PO : 81714	STYLE NO. & DESC. Smart Lock
PRODUCTION MATERIAL / CONSTRUCTION Aluminum alloy, Plastic, Stainless Steel	STYLE COLOR & CODE Prime Black
INSPECTION IMAGES LINK NA	TOTAL CARTONS NA

TOTAL INSPECTED QTY (AS PER AQL LEVEL)

50 PCS

of 350 PCS

INSPECTION RESULT

PASS



ISSUE TYPE NO. OF ISSUES FOUND	STATUS & AQL LEVEL	ACCEPTED DEFECT LIMITS BY AQL
MAJOR DEFECTS 0	ACCEPTED defects within NA	upto 3 defects allowed
MINOR DEFECTS 2	ACCEPTED defects within NA	upto 5 defects allowed
CRITICAL DEFECTS Nil	ACCEPTED defects within AQL 0.1	upto 0 defects allowed

SILQ'S OBSERVATION	REMARKS
WORKMANSHIP <small>(as per AQL Level)</small>	OK
PRODUCT CONFORMITY	OK
MEASUREMENTS	OK
ONSITE TESTS	OK
PACKING	OK

NOTES & COMMENTS

1. No approval sample provided for inspection.
2. PO / Tech Files / Measurement Chart recieved from Client.
3. Client to confirm release of goods.
4. This is 100% Inspection - No AQL level tolerance.
5. No measurement tolerance provided, found measurement +/- 2cm.
6. Goods not yet packed.
7. Found style GBT_TH_SW2 navy part the color not same as tech files.
8. Client provided measurement chart missed size 4XL and 5XL, used factory measurement for inspection.

The Defects found by the Silq QC during inspection was shown to the factory - The Silq QC advised factory to Repair/Replace/ Reject these defects before dispatch of the goods

SILQ ID
SILQ-1234567

REVIEW DATE
04.16.2026

REPORT DATE
04.15.2026

SILQ INSPECTOR
Peter YANG

SECONDARY REVIEW BY
Mr. Sundar
Senior Manager - Global Inspections

FACTORY REPRESENTATIVE / DESIGNATION
Minhan Zhang

PRODUCT CONFORMITY (IN COMPARISON TO APPROVED SAMPLE AND TECH PACK INSTRUCTIONS)

DESCRIPTION	CONFORMITY	REMARKS
Product Design / Model	CONFORM	
Product Build Quality	CONFORM	
Product Colour	CONFORM	
Product Finish - (Matte / Shiny)	CONFORM	
TT Lock Check	CONFORM	
Adhesive Test on Logo / Painting	CONFORM	
Assembli Test	CONFORM	
Load Test	CONFORM	
Battery Fitting / Reverse Test	CONFORM	
Fatigue Test	CONFORM	
Internal Check	CONFORM	
Touch Sensor (Finger Print)	CONFORM	
WIFI Connectivity	CONFORM	
APP Connectivity	CONFORM	
Remote Work	CONFORM	
Manual Key	CONFORM	



PRODUCT CONFORMITY IMAGES - ACCESSORIES AND TRIMS



PRODUCT VIEW - 1



PRODUCT VIEW - 2




PRODUCT VIEW - 3



PRODUCT VIEW - 4



PRODUCT VIEW - 5



PRODUCT VIEW - 6


PRODUCT CONFORMITY IMAGES - ACCESSORIES AND TRIMS



PRODUCT VIEW - 7



PRODUCT VIEW - 8



PRODUCT VIEW - 9



PRODUCT VIEW - 10



PRODUCT VIEW - 11



PRODUCT VIEW - 12

PRODUCT CONFORMITY IMAGES



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW




PRODUCT VIEW



PRODUCT VIEW

PRODUCT CONFORMITY IMAGES



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW



PRODUCT VIEW - KEYS



PRODUCT VIEW - CARD



PRODUCT VIEW - BATTERY

ONSITE TESTS IMAGES



HANDLE CHECK



HANDLE CHECK



HANDLE CHECK



ASSEMBLY CHECK



ASSEMBLY CHECK



CURRENT CHECK

ONSITE TESTS IMAGES



CURRENT CHECK




CURRENT CHECK



CURRENT CHECK



TT LOCK CHECK




TT LOCK CHECK



TT LOCK CHECK


ONSITE TESTS IMAGES



TT LOCK CHECK




TT LOCK CHECK



TT LOCK CHECK



3M TAPE CHECK ON LOGO



3M TAPE CHECK ON LOGO



LOGO SIZE CHECK

ONSITE TESTS IMAGES




LOGO SIZE CHECK



EMERGENCY CHARGING CHECK



UNLOCKING CHECK WITH CARD



UNLOCKING CHECK WITH CARD



UNLOCKING CHECK WITH CARD



UNLOCKING CHECK WITH CARD





DEFECT IMAGES



MINOR
Glue Mark



MINOR
Stain



PACKING AUDIT

DESCRIPTION	DETAILS	REMARKS
Order Quantity	350 sets	
Packed Quantity	350 sets	
Quantity Remarks - Shortage / Excess	N/A	
Quantity Shortage/Excess Approval from Client	N/A	
Total Cartons	70 ctns	
Carton Numbers	1 - 70	
Final Packing Approval from Client	YES	
Packing Status at the time of Inspection - Is it 100% packed?	YES	
If " Packing" status is NO, Cartons Packed / % Packed:	N/A	
Carton Dimension (as per requirement)	YES	
Carton Marking - Length Side	OK	
Carton Marking - Width Side	OK	
Carton Quality	OK	
Polybag Quality	OK	
Polybag Size	OK	
Carton Weight within specified acceptable limits	YES	
Total Cartons Inspected	10	
Carton Sizes Used	OK	60 x 40 x 40 cms

PACKING IMAGES



CARTON VIEW



CARTON VIEW




CARTON BARCODE STICKERS



CARTON INSIDE



CARTON INSIDE



PRODUCT BOX PACKING

PACKING IMAGES



ACCESSORIES PRESENT IN THE BOX



ACCESSORIES PRESENT IN THE BOX



ACCESSORIES PRESENT IN THE BOX



SCREW PACKING



CARTON



PRODUCT PACKING