


# SAMPLE INSPECTION REPORT

Comprehensive Sample Assessment

**FACTORY NAME : KSHOES - VIETNAM**



Powered by Silq Inspection Services

For more information visit [www.onesilq.com/inspections](http://www.onesilq.com/inspections)

# Silq Sample Inspection Report

Comprehensive Sample Assessment

Sample Overview		
Sample Received On Time	YES	
Correct Quantity Of Samples	YES	
Correct Size Submitted	YES	Sample Size - 9
Matching Tech Details	YES	
Sample Clearly Labeled	YES	
Overall Aesthetic Appearance	YES	

Material and Quality Check		
Product Quality	OK	
Product Colour	OK	
Leather Thickness	OK	
Mounting Components Quality	OK	
Product Pairing Shade / Size	OK	

Construction & Dimension		
Thickness Of Material	OK	
Sole Bonding Strength	OK	
Mounting Holes Spacing	NA	
Edge Finishing	OK	
Flexibility	OK	
Overall Dimensions	OK	

Trims, Accessories & Labelling		
Brand Logo & Labels	OK	
Logo Position	OK	
Logo Colour	OK	
Product Size	OK	

Functionality & Check		
Stability	OK	
Strap Strength	NA	
Buckle Lock	NA	
Comfort Check	OK	

Packing Quality & Presentation		
Product Packed as Required	YES	
Correct Size Sticker	YES	
Labeling And Marking	YES	
Clean And Presentable Packing	YES	



General Information	
INSPECTION DATE	02-20-2026
FACTORY NAME & ADDRESS	KSHOES - VIETNAM
BUYER/BRAND	KURU
PURCHASE ORDER NO.	KFSLP0224007
STYLE NO. / ARTICLE NO.	CV140911 / SLD0175
ITEM DESCRIPTION	WOMENS SANDALS
SUBMISSION DATE	02-20-2026
SAMPLE TYPE	PRE-PRODUCTION SAMPLE
SAMPLE RESULT	APPROVED



# Silq Sample Inspection Report

Comprehensive Sample Assessment



SAMPLE IMAGES COLLECTED BY SILO



SAMPLE FRONT VIEW



SAMPLE BACK VIEW



SAMPLE SIDE VIEW



SAMPLE SIDE VIEW



SAMPLE SIDE VIEW



SAMPLE BACK VIEW

# Silq Sample Inspection Report


Comprehensive Sample Assessment



SAMPLE IMAGES COLLECTED BY SILQ



SAMPLE LOGO



SAMPLE METAL LOGO & SIZE



SAMPLE LABEL PRINTING



SAMPLE HEEL VIEW

NIL

NIL