

DUPRO INSPECTION REPORT

Comprehensive Mid-Production Assessment

Factory: **SEN LEATHER**



Powered by Silq Inspection Services
For more information visit www.onesilq.com/inspections

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment

Quality Checkpoints		
Body Colour	OK	
Shade Check	OK	
Sewing Quality check	OK	
Matching Client's tech pack/spec	OK	
Compared to Approved Sample	OK	

Material Check		
Body Material quality	OK	
Material Weight as required	OK	
Color shade matches standard	OK	
Material Touch Handfeel	OK	
Body Material Odour	OK	

Artwork Check		
Lambert Logo Artwork Quality	OK	
Lambert Logo Artwork Colour	OK	
Lambert Logo Artwork Size / Placement	OK	
Style name Artwork Quality	OK	
Style name placement	OK	
Lambert Artwork evenness	OK	

Trims, Accessories & Labelling		
Main Label	OK	
Wash Care Label	OK	
TSSA/COO Label	OK	
Placement of labels	OK	
Lining colour	OK	
Lining Quality	OK	
Swivel Hooks / Lobster Clasps	OK	
D-Ring / Lock / Handle / Wheels / Trolley Handle	OK	
Buckle / Slider Buckle / Tri-glide / Velcro	OK	
Strap Loop Keeper / Zipper	OK	
Hangtags / Barcode Sticker	NA	
Polybag size / Quality / Handle warp	NA	



General Information

FACTORY NAME
SEN LEATHER

BUYER/BRAND
SILQ

INSPECTION DATE
1/29/2026

PURCHASE ORDER NO.
04724

STYLE NO. / ARTICLE NO.
JOLIE

ITEM DESCRIPTION
Plastic cosmetic bag

PRODUCT MATERIAL
Exterior coating - 100% Polyurethane
Exterior base fabric: 100% Recycled Polyester
Lining: 100% Recycled Polyester

COLOUR
BLACK, CLAY

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment



Functionality Check	Zipper / Puller / Handle	OK
	Snap buttons / Velcro / Wheels/ Trolley Handle	OK
	Adjuster Buckle / Slider Buckle Swivel Hook / Loop Keeper	OK
	Overall aesthetic appeal	OK

Packing Quality & Presentation	Packing as per Lambert requirements	NA
	Carton Quality	NA
	Carton Size	NA
	Carton Marking	NA

Inspection Summary	Operation Being Inspected	:
	Production Status (%)	: Cutting 100% finished; Edge painting 100% finished; Just start sewing ; Not yet packing.
	Total Qty Inspected in In-Line	: 5 pcs per color, total 10pcs
	Overall Product Quality Status	:

For Internal use only by Silq

SILQ ID
Silq-6282129

SILQ INSPECTOR
WOLKER HUANG

REVIEW DATE
1/29/2026

SECONDARY REVIEW BY

Mr. Sundar
Senior Manager
Global Inspections

Inspector Comments & Recommendations

SILQ QC HIGHLIGHTED THE DEFECTS IDENTIFIED DURING THE IN-LINE INSPECTION, EXPLAINED THEM TO THE FACTORY IN DETAIL, AND INSTRUCTED THE FACTORY TO RECTIFY ALL THE ABOVE-MENTIONED ISSUES BEFORE THE FINAL INSPECTION

Silq In-line Inspection Report

Comprehensive Mid-Production Assessment

Part Dimensions	Unit	Tol. Limit	MEASUREMENTS		
	Cms	+ / -	ONE SIZE	I	II
		Spec			
Bag length			22.5	0	0
Bag width			9	0	0
Bag height			12.5	0	0
Handle length			17	0	0

MEASUREMENT COMMENTS :

- 1. The Measurements are found within tolerance

GENERAL IMAGES



FORNT VIEW



BACK VIEW



SIDE VIEW



SIDE VIEW



TOP VIEW



BOTTOM VIEW

GENERAL IMAGES



INSIDE VIEW



INSIDE VIEW



STYLE NAME



TSSA/COO LABEL



STYLE NAME



TSSA/COO LABEL


GENERAL IMAGES



LOGO




LOGO



ZIPPER PULLER



STUD



COLOR CHECKING



COLOR CHECKING

GENERAL IMAGES



APPROVED SAMPLE VS BULK



APPROVED SAMPLE VS BULK

DEFECT IMAGES



Findings : Exposed plate
Corrective Action : Factory needs to improve by assembling

NA

Findings :
Corrective Action :

NA

Findings :
Corrective Action :

NA

Findings :
Corrective Action :

NA

Findings :
Corrective Action :

NA

Findings :
Corrective Action :