


FACTORY INSPECTION REPORT

Comprehensive on-site assessment

ROYAL SYNTHETICS INDIA PVT LTD, LUDHIANA, INDIA



Factory Inspection Report

Comprehensive on-site assessment



Client Information	Customer Name	EZRASONS
	Customer Contact	Mr.Ramar
	Inspected By	Narahari Ojha
	Inspector ID	SILQ-i10521

Factory Address / Contact	Factory Name	Royal Synthetics India Pvt Ltd.
	Factory Contact	Mr.Miglani
	Factory Address	B-XXXII, E-10-27, KALI SARAK, CHENNAI, INDIA 141008.
	Inspection Date	12/26/2025
	Inspection City	Chennai, India

Factory Information <small>(verified by silq)</small>	Year Founded	2022	# of Employees	212
	Founder / Owner	Mr.Miglani	Company Legal Structure	Proprietorship
	Business License	LDHOFL007740	Import License	AKIPM4040J
	Business License Validity	31ST DEC 2029	Export License	AKIPM4040J
	Nearest Seaport	Mundra, India	Nearest Airport	Delhi, India
	2025 Export Vol. (PCS)	1,700,000 PCS	Primary Mkts. Served	US, EU, MEA
	2025 Total Revenue	2,700,000 USD	2025 Export Revenue	2,000,000 USD
	Pref. Shipment Terms	FOB	Pref. Payment Terms	LC
	Production Lead Times	75 days	GOTS Certification	Yes
	Fair Trade Certification	No	OEKOTEX Certified	No
	ISO Certification	Yes	GMP Certification	No
	FAMA Certification	No	Bank	SBI Bank, India

Manufacturing Capabilities <small>(verified by silq)</small>	Manufacturing Type	Apparels-Knitted	No.Of Machines	100 Nos - Sewing Machines
	Other Company-Owned Facilities	Knitting Machines	No.Of Machines	4 Nos - Jersey Machines
	Other Company-Owned Facilities	Dyeing Machine	No.Of Machines	2 Nos, 300 Kgs,500 Kgs
	Other Company-Owned Facilities	Automatic Printing Machine	No.Of Machines	2 Nos , MHM
	Other Company-Owned Facilities	Embroidery Machines	Nearest Airport	3 Nos - Tajima 20 Heads

Factory Inspection Report

Comprehensive on-site assessment



Export Track Record <small>(verified by Silq)</small>	MAIN PRODUCT	PRODUCTION QTY	PERCENTAGE	MAIN EXPORT MKTS	MAIN CLIENTS
	MENS - ROUND NECK T-SHIRT	1,50,000	8%	USA	LORENCY & CO
	MENS - ROUND NECK T-SHIRT	1,50,000	8%	USA	BOBEN TRADING
	MENS POLIOS	13,25,000	70%	EUROPE	JINZU CLOTHING
	MIXED PRODUCTS	75,000	4%	INDIA	RELIANCE
	MENS V NECK T-SHIRT	1,90,000	10%	USA	TARGET
Shipment Volume (in pcs) / Frequency		400,000 pcs every 3 months			
Shipment Delays		10-15% Delays			

Factory Inspection Report

Comprehensive on-site assessment



FACTORY CHECKLIST VERIFIED BY SILQ

Operational & Production Capabilities	Owned & Operated Facility	YES	Factory has its own building
	Third Party / Trading Company	NO	Manufacturer with its own facilities
	Fire & Carbon Monoxide Detection System	NO	Annual Inspection Certificates Reviewed and up to date
	Child Labor Sighting	NO	No Child Labour Found in the Factory Premises at the time of inspection
	Needle Detector Machine Available	YES	Yes, the machine was in use during inspection
	Material Sourcing (Do they Import from China or Other Countries)	YES	Elastane Fabrics are imported. Cotton Fabrics and accessories sourced locally
	Equipment List	YES	50 Over lock machines / 25 Flat Lock Machines /
	In-House Dyeing Unit	YES	Factory has its own Dyeing Plant in-house
	Filtered Drinking Water & Lunch Room Facilities	YES	Factory has installed a captive RO Plant for filtered water that is inspected annually
	Gender Specific Sanitary Bathroom Facilities	YES	Gender Specific Bathroom Facilities with shower stalls on-site
Compliance & Risk	Active Employee Benefits Program	YES	Tenured employees participate in company sponsored Provident Fund Program
	On-Site Lab Facilities	YES	In-House Lab for testing with a light box, punching machine and color spectrometer
	ISO / SA8000 / FAMA / CEDEX	YES	ISO / FAMA - Certified
	Environmental Practices	YES	Captive water treatment plant and scrubber in compliance with local standards
	Air Emission/Exhaust Scrubbers	NO	
Strategic Fit	Financial Reliability	NO	No risk was detected based on available information at the time of inspection
	Fire Safety Measures	YES	Clearly marked Fire Exits and centrally controlled sprinkler system present
	Other Categories Produce	NO	Factory Produces only Garments
Quality Control Infrastructure <small>(verified by silq)</small>	Flexibility With & MOQ's & Customization	YES	Factory stated flexibility on MoQ's for current customers
	Communication & Language Capabilities	YES	Factory Can Communicate in Tamil / Hindi & English
	Competitor Factories Nearby	YES	Yes, There are 4 Firms nearby
	Verify Accessible Reference/Approved Sample Library	YES	Yes. Merchandising office has a filing system with version control in use
	Verify approved sample available in-line for reference	YES	Line supervisors have reference samples made available to tailors during production
	Verify Broken Needle Record Book Maintained	YES	Yes. However the record book is maintained manually and not digitally stored
	Verify Internal Lab Testing Records Maintained	YES	Yes. Testing records are printed and filed with the merchandising office
	Verify Final QC is done prior to packing	YES	Yes. In-house inspectors perform random inspection prior to packing

Factory Inspection Report

Comprehensive on-site assessment



OVERALL EVALUATION BY SILQ

Overall Score	General Organization & Housekeeping	9	Factory outsources maintenance and cleaning, resulting in well maintained facilities
	Working Environment (Light, Dust, Noise, etc.)	9	Factory uses energy efficient LED lights and industrial fans for air circulation
	Maintenance of Production Equipment & Facilities	9	Machines were found to be in good condition during the time of inspection
	Employee Safety & First Aid Infrastructure	8	Yes. Centrally controlled fire sprinklers present. First Aid kit available in the office
	Stock Room Upkeep	8	Stock room was overstocked, showing signs of disorder
	Quality Control Infrastructure & Processes	6	Factory lacked digitally maintained QC Logs for inspection
Overall Rating		8	

Factory Inspection Report

Comprehensive on-site assessment



Management Systems & Product Certifications

(verified by Silq)

(verified by Silq)

Certificate Name

GST (REG-06)

 Government of India - 9999999999 Ministry of Commerce and Industry Directorate General of Foreign Trade - Ministry of Commerce Office of the Administrator, 10th Floor, DLF Cyber City, Sector 9, Noida-201301, Uttar Pradesh, India Phone: +91-120-45678900, Fax: +91-120-45678901 Email: dgft@mea.gov.in Nayan Bhansali, DSN, Trade Control Officer, T-200, 10th Floor, DLF Cyber City, Sector 9, Noida-201301, Uttar Pradesh, India Phone: +91-9810000000, Email: nayan.bhansali@mea.gov.in	
Importers license code	
This is to certify that ROYAL SYNTHETICS is issued as Importer Export Code (IEC) APK9999999999 with details as below:	
IEC	APK9999999999
and IEC in other PAN	APK9999999999
and its IEC Name	ROYAL SYNTHETICS
Show IEC with Details of Commissioners	21/9/2022
and IEC with Details of Commissioner	
Mythological Name	Suresh Shrivastava, 8-10-27, Kasturi, Ludhiana, Punjab, 141001, INDIA
State / Name of the Signatory	SHUBHAM SHIVANI
Signatory Person Details	Address of Signatory: 8-10-27, Kasturi, Ludhiana, Punjab, 141001, INDIA Email Address of Signatory: shubham.shivani@royalsynthetics.com
and IEC with Details of Signatory	
I am / Modified / File Number : DGFT.GOV.IN/MSMS/1123456789	

Certificate Name

IEC (IMPORTER-EXPORTER)

Certificate Name

Factory License (1948)

The image shows a certificate of registration for Zhaihuai Siwei New Material Technology Co., Ltd. The certificate is issued by AMTIVO. It includes the company's name, address, and various seals and signatures.

Certificate Name

ISO 9001:2015

Certificate Name

ISO 14001:2015

Certificate Name

ISO 45001:2018

Factory Inspection Report

Comprehensive on-site assessment



FACTORY LAYOUT & WORKING CONDITIONS **VERIFIED BY SILQ**



Factory Name Board




Factory Building



Meeting Room



Office



Merchandizing Office



Stock Room

Factory Inspection Report

Comprehensive on-site assessment



PRODUCTION LINE VERIFIED BY SILQ



Production Line - 1



Production Line - 2



Production Line - 3



Production Line - 4



QC Table



In-House Lab

Factory Inspection Report

Comprehensive on-site assessment



GENERAL IMAGES



Packing Table



Sampling Room



Packing Section



Carton Storage Warehouse

Factory Inspection Report

Comprehensive on-site assessment



NOTES & COMMENTS FROM SILQ

1. Factory has knitting Unit & Dyeing plant - 30 kms away from the Factory
2. Silq QC Checked few pcs from the Production line and the Qulaity seems to be Good

FOR INTERNAL USE ONLY BY SILQ

Silq ID Silq-6251034

Report Date 12/24/2025

Silq Inspector Ojha

Secondary Review By Silq Manager Sundar - Senior Manager Global Inspections

Review Date 12/26/2025